

Section II
Soil and Site Information

Construction Materials Table 2
Gregory County, South Dakota

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The ratings given for the thickest layer are for the thickest layer above and excluding the bottom layer. The numbers in the value columns range from 0.00 to 0.99. The greater the value, the greater the likelihood that the bottom layer or thickest layer of the soil is a source of sand or gravel. See text for further explanation of ratings in this table.)

Map symbol and soil name	Pct. of map unit	Potential source of reclamation material		Potential source of roadfill		Potential source of topsoil	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
AaA: Agar-----	90	Good		Poor Low strength Shrink-swell	0.00 0.87	Good	
AaB: Agar-----	90	Good		Poor Low strength Shrink-swell	0.00 0.87	Good	
AdC: Anselmo-----	60	Fair Low content of organic matter	0.88	Fair Depth to bedrock	0.58	Good	
Dunday-----	30	Poor Too sandy Wind erosion Low content of organic matter Droughty	0.00 0.00 0.12 0.92	Good		Poor Too sandy	0.00
AhB: Anselmo-----	55	Fair Low content of organic matter	0.88	Fair Depth to bedrock	0.58	Good	
Holt-----	30	Fair Droughty Depth to bedrock	0.27 0.58	Poor Depth to bedrock	0.00	Fair Depth to bedrock	0.58
AhC: Anselmo-----	50	Fair Low content of organic matter	0.88	Fair Depth to bedrock	0.58	Good	
Holt-----	40	Fair Droughty Depth to bedrock	0.27 0.58	Poor Depth to bedrock	0.00	Fair Depth to bedrock	0.58

Section II
Soil and Site Information

Construction Materials Table 2
Gregory County, South Dakota

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The ratings given for the thickest layer are for the thickest layer above and excluding the bottom layer. The numbers in the value columns range from 0.00 to 0.99. The greater the value, the greater the likelihood that the bottom layer or thickest layer of the soil is a source of sand or gravel. See text for further explanation of ratings in this table.)

Map symbol and soil name	Pct. of map unit	Potential source of reclamation material		Potential source of roadfill		Potential source of topsoil	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
AtE: Anselmo-----	60	Fair Low content of organic matter	0.88	Fair Depth to bedrock Slope	0.58 0.98	Poor Slope	0.00
Tassel-----	30	Poor Droughty Depth to bedrock	0.00 0.00	Poor Depth to bedrock Slope	0.00 0.98	Poor Depth to bedrock Slope	0.00 0.00
BaE: Betts-----	85	Fair Low content of organic matter Carbonate content Water erosion	0.12 0.92 0.99	Poor Slope Low strength Shrink-swell	0.00 0.00 0.87	Poor Slope Salinity Carbonate content	0.00 0.88 0.92
Bb: Bon-----	85	Fair Low content of organic matter	0.50	Fair Low strength	0.22	Good	
Bc: Bon-----	75	Fair Low content of organic matter	0.50	Fair Low strength	0.22	Good	
B1D: Boro-----	50	Poor Too clayey Low content of organic matter Water erosion	0.00 0.50 0.99	Poor Shrink-swell Low strength	0.00 0.00	Poor Too Clayey Slope	0.00 0.37
Lakoma-----	35	Poor Too clayey Droughty Depth to bedrock Carbonate content Water erosion	0.00 0.00 0.58 0.80 0.99	Poor Depth to bedrock Low strength Shrink-swell	0.00 0.00 0.00	Poor Too Clayey Slope Depth to bedrock Carbonate content	0.00 0.37 0.58 0.80

Section II
Soil and Site Information

Construction Materials Table 2
Gregory County, South Dakota

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The ratings given for the thickest layer are for the thickest layer above and excluding the bottom layer. The numbers in the value columns range from 0.00 to 0.99. The greater the value, the greater the likelihood that the bottom layer or thickest layer of the soil is a source of sand or gravel. See text for further explanation of ratings in this table.)

Map symbol and soil name	Pct. of map unit	Potential source of reclamation material		Potential source of roadfill		Potential source of topsoil	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
BmB: Boro-----	60	Poor Too clayey Low content of organic matter Water erosion	0.00 0.50 0.99	Poor Shrink-swell Low strength	0.00 0.00	Poor Too Clayey	0.00
Millboro-----	35	Poor Too clayey Low content of organic matter Water erosion	0.00 0.12 0.99	Poor Shrink-swell Low strength	0.00 0.00	Poor Too Clayey	0.00
BmC: Boro-----	60	Poor Too clayey Low content of organic matter Water erosion	0.00 0.50 0.99	Poor Shrink-swell Low strength	0.00 0.00	Poor Too Clayey	0.00
Millboro-----	35	Poor Too clayey Low content of organic matter Water erosion	0.00 0.12 0.99	Poor Shrink-swell Low strength	0.00 0.00	Poor Too Clayey	0.00
CaA: Carter-----	55	Poor Too clayey Low content of organic matter Sodium content Water erosion	0.00 0.12 0.22 0.99	Poor Shrink-swell Low strength	0.00 0.00	Poor Too Clayey Sodium content Salinity	0.00 0.22 0.88
Capa-----	35	Poor Too clayey Sodium content Low content of organic matter Salinity Water erosion	0.00 0.00 0.12 0.88 0.99	Poor Shrink-swell Low strength	0.00 0.00	Poor Too Clayey Sodium content Salinity	0.00 0.00 0.00

Section II
Soil and Site Information

Construction Materials Table 2
Gregory County, South Dakota

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The ratings given for the thickest layer are for the thickest layer above and excluding the bottom layer. The numbers in the value columns range from 0.00 to 0.99. The greater the value, the greater the likelihood that the bottom layer or thickest layer of the soil is a source of sand or gravel. See text for further explanation of ratings in this table.)

Map symbol and soil name	Pct. of map unit	Potential source of reclamation material		Potential source of roadfill		Potential source of topsoil	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
CbA: Carter-----	60	Poor Too clayey Low content of organic matter Sodium content Water erosion	0.00 0.12 0.22 0.99	Poor Shrink-swell Low strength	0.00 0.00	Poor Too Clayey Sodium content Salinity	0.00 0.22 0.88
Promise-----	35	Poor Too clayey Low content of organic matter Water erosion	0.00 0.12 0.99	Poor Shrink-swell Low strength	0.00 0.00	Poor Too Clayey	0.00
Cd: Cass-----	90	Fair Low content of organic matter	0.88	Good		Good	
CrC: Coly-----	85	Fair Low content of organic matter Water erosion	0.88 0.90	Fair Low strength	0.22	Good	
CrE: Coly-----	80	Fair Low content of organic matter Water erosion	0.88 0.90	Fair Low strength Slope	0.22 0.92	Poor Slope	0.00
DaA: Dunday-----	90	Poor Too sandy Wind erosion Low content of organic matter Droughty	0.00 0.00 0.12 0.92	Good		Poor Too sandy	0.00

Section II
Soil and Site Information

Construction Materials Table 2
Gregory County, South Dakota

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The ratings given for the thickest layer are for the thickest layer above and excluding the bottom layer. The numbers in the value columns range from 0.00 to 0.99. The greater the value, the greater the likelihood that the bottom layer or thickest layer of the soil is a source of sand or gravel. See text for further explanation of ratings in this table.)

Map symbol and soil name	Pct. of map unit	Potential source of reclamation material		Potential source of roadfill		Potential source of topsoil	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
Du: Durrstein-----	90	Poor Sodium content Too clayey Low content of organic matter Salinity Water erosion	0.00 0.00 0.12 0.88 0.99	Poor Depth to saturated zone Low strength Shrink-swell	0.00 0.00 0.12	Poor Sodium content Depth to saturated zone Too Clayey Salinity	0.00 0.00 0.00 0.00
Fd: Fedora-----	90	Fair Carbonate content	0.46	Poor Depth to saturated zone	0.00	Poor Depth to saturated zone	0.00
Ha: Haynie Variant-----	55	Fair Low content of organic matter Water erosion	0.12 0.99	Poor Low strength	0.00	Good	
Munjor-----	35	Fair Low content of organic matter Carbonate content	0.12 0.92	Good		Fair Carbonate content	0.92
HoA: Holt-----	85	Fair Droughty Depth to bedrock	0.27 0.58	Poor Depth to bedrock	0.00	Fair Depth to bedrock	0.58
HoB: Holt-----	85	Fair Droughty Depth to bedrock	0.27 0.58	Poor Depth to bedrock	0.00	Fair Depth to bedrock	0.58
HoC: Holt-----	90	Fair Droughty Depth to bedrock	0.27 0.58	Poor Depth to bedrock	0.00	Fair Depth to bedrock	0.58

Section II
Soil and Site Information

Construction Materials Table 2
Gregory County, South Dakota

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The ratings given for the thickest layer are for the thickest layer above and excluding the bottom layer. The numbers in the value columns range from 0.00 to 0.99. The greater the value, the greater the likelihood that the bottom layer or thickest layer of the soil is a source of sand or gravel. See text for further explanation of ratings in this table.)

Map symbol and soil name	Pct. of map unit	Potential source of reclamation material		Potential source of roadfill		Potential source of topsoil	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
HoD: Holt-----	85	Fair Droughty Depth to bedrock	0.27 0.58	Poor Depth to bedrock	0.00	Fair Slope Depth to bedrock	0.37 0.58
Ia: Inavale-----	90	Poor Too sandy Wind erosion Low content of organic matter Droughty	0.00 0.00 0.12 0.88	Good		Poor Too sandy	0.00
InB: Inavale-----	85	Poor Wind erosion Droughty Low content of organic matter Too sandy	0.00 0.12 0.12 0.28	Good		Fair Too sandy	0.28
Ix: Norway-----	90	Poor Wind erosion Too sandy Low content of organic matter Droughty	0.00 0.11 0.12 0.35	Poor Depth to saturated zone	0.00	Poor Depth to saturated zone Too sandy	0.00 0.11
JaA: Jansen-----	85	Fair Low content of organic matter Too acid Water erosion	0.12 0.97 0.99	Good		Fair Hard to reclaim	0.98
JaB: Jansen-----	85	Fair Low content of organic matter Too acid Water erosion	0.12 0.97 0.99	Good		Fair Hard to reclaim	0.98

Section II
Soil and Site Information

Construction Materials Table 2
Gregory County, South Dakota

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The ratings given for the thickest layer are for the thickest layer above and excluding the bottom layer. The numbers in the value columns range from 0.00 to 0.99. The greater the value, the greater the likelihood that the bottom layer or thickest layer of the soil is a source of sand or gravel. See text for further explanation of ratings in this table.)

Map symbol and soil name	Pct. of map unit	Potential source of reclamation material		Potential source of roadfill		Potential source of topsoil	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
JaC: Jansen-----	90	Fair Low content of organic matter Too acid Water erosion	0.12 0.97 0.99	Good		Fair Hard to reclaim	0.98
JbA: Jansen-----	65	Fair Low content of organic matter Too acid Water erosion	0.12 0.97 0.99	Good		Fair Hard to reclaim	0.98
Brocksburg-----	25	Fair Low content of organic matter	0.12	Good		Fair Hard to reclaim	0.92
Ko: Kolls-----	90	Poor Too clayey Water erosion	0.00 0.99	Poor Shrink-swell Low strength Depth to saturated zone	0.00 0.00 0.00	Poor Too Clayey Depth to saturated zone	0.00 0.00
LaB: Labu-----	85	Poor Too clayey Droughty Depth to bedrock Low content of organic matter	0.00 0.03 0.58 0.88	Poor Depth to bedrock Low strength Shrink-swell	0.00 0.00 0.00	Poor Too Clayey Depth to bedrock	0.00 0.58
LaC: Labu-----	85	Poor Too clayey Droughty Depth to bedrock Low content of organic matter	0.00 0.03 0.58 0.88	Poor Depth to bedrock Low strength Shrink-swell	0.00 0.00 0.00	Poor Too Clayey Depth to bedrock	0.00 0.58

Section II
Soil and Site Information

Construction Materials Table 2
Gregory County, South Dakota

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The ratings given for the thickest layer are for the thickest layer above and excluding the bottom layer. The numbers in the value columns range from 0.00 to 0.99. The greater the value, the greater the likelihood that the bottom layer or thickest layer of the soil is a source of sand or gravel. See text for further explanation of ratings in this table.)

Map symbol and soil name	Pct. of map unit	Potential source of reclamation material		Potential source of roadfill		Potential source of topsoil	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
LaD: Labu-----	85	Poor Too clayey Droughty Depth to bedrock Low content of organic matter	0.00 0.03 0.58 0.88	Poor Depth to bedrock Low strength Shrink-swell	0.00 0.00 0.00	Poor Too Clayey Slope Depth to bedrock	0.00 0.37 0.58
LcF: Labu-----	45	Poor Too clayey Droughty Depth to bedrock Low content of organic matter	0.00 0.03 0.58 0.88	Poor Depth to bedrock Low strength Shrink-swell Slope	0.00 0.00 0.00 0.08	Poor Slope Too Clayey Depth to bedrock	0.00 0.00 0.58
Sansarc-----	40	Poor Too clayey Droughty Depth to bedrock Low content of organic matter Water erosion	0.00 0.00 0.00 0.60 0.99	Poor Depth to bedrock Shrink-swell Low strength Slope	0.00 0.00 0.00 0.00	Poor Slope Too Clayey Depth to bedrock	0.00 0.00 0.00
LoD: Lakoma-----	65	Poor Too clayey Droughty Depth to bedrock Carbonate content Water erosion	0.00 0.00 0.58 0.80 0.99	Poor Depth to bedrock Low strength Shrink-swell	0.00 0.00 0.00	Poor Too Clayey Slope Depth to bedrock Carbonate content	0.00 0.37 0.58 0.80
Okaton-----	35	Poor Too clayey Droughty Depth to bedrock Water erosion	0.00 0.00 0.00 0.99	Poor Depth to bedrock Shrink-swell Low strength	0.00 0.00 0.00	Poor Too Clayey Depth to bedrock Slope	0.00 0.00 0.37

Section II
Soil and Site Information

Construction Materials Table 2
Gregory County, South Dakota

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The ratings given for the thickest layer are for the thickest layer above and excluding the bottom layer. The numbers in the value columns range from 0.00 to 0.99. The greater the value, the greater the likelihood that the bottom layer or thickest layer of the soil is a source of sand or gravel. See text for further explanation of ratings in this table.)

Map symbol and soil name	Pct. of map unit	Potential source of reclamation material		Potential source of roadfill		Potential source of topsoil	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
LwB: Lakoma-----	45	Poor Too clayey Droughty Depth to bedrock Carbonate content Water erosion	0.00 0.00 0.58 0.80 0.99	Poor Depth to bedrock Low strength Shrink-swell	0.00 0.00 0.00	Poor Too Clayey Depth to bedrock Carbonate content	0.00 0.58 0.80
Wewela-----	30	Fair Droughty Depth to bedrock Water erosion	0.49 0.58 0.99	Poor Depth to bedrock Shrink-swell	0.00 0.54	Fair Depth to bedrock	0.58
LwC: Lakoma-----	50	Poor Too clayey Droughty Depth to bedrock Carbonate content Water erosion	0.00 0.00 0.58 0.80 0.99	Poor Depth to bedrock Low strength Shrink-swell	0.00 0.00 0.00	Poor Too Clayey Depth to bedrock Carbonate content	0.00 0.58 0.80
Wewela-----	30	Fair Droughty Depth to bedrock Water erosion	0.49 0.58 0.99	Poor Depth to bedrock Shrink-swell	0.00 0.54	Fair Depth to bedrock	0.58
M-W: Miscellaneous Water Area-----	100	Not rated		Not rated		Not rated	
MaD: Mariaville-----	100	Poor Depth to bedrock Droughty Low content of organic matter Water erosion	0.00 0.00 0.88 0.90	Poor Depth to bedrock Low strength	0.00 0.00	Poor Depth to bedrock Slope	0.00 0.63

Section II
Soil and Site Information

Construction Materials Table 2
Gregory County, South Dakota

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The ratings given for the thickest layer are for the thickest layer above and excluding the bottom layer. The numbers in the value columns range from 0.00 to 0.99. The greater the value, the greater the likelihood that the bottom layer or thickest layer of the soil is a source of sand or gravel. See text for further explanation of ratings in this table.)

Map symbol and soil name	Pct. of map unit	Potential source of reclamation material		Potential source of roadfill		Potential source of topsoil	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
MaF: Mariaville-----	85	Poor Depth to bedrock Droughty Low content of organic matter Water erosion	0.00 0.00 0.88 0.90	Poor Depth to bedrock Slope Low strength	0.00 0.00 0.00	Poor Slope Depth to bedrock	0.00 0.00
MdF: Mariaville-----	40	Poor Depth to bedrock Droughty Low content of organic matter Water erosion	0.00 0.00 0.88 0.90	Poor Depth to bedrock Slope Low strength	0.00 0.00 0.00	Poor Slope Depth to bedrock	0.00 0.00
Labu-----	25	Poor Too clayey Droughty Depth to bedrock Low content of organic matter	0.00 0.03 0.58 0.88	Poor Depth to bedrock Low strength Shrink-swell Slope	0.00 0.00 0.00 0.08	Poor Slope Too Clayey Depth to bedrock	0.00 0.00 0.58
Anselmo-----	15	Fair Low content of organic matter	0.88	Fair Slope Depth to bedrock	0.08 0.58	Poor Slope	0.00
MeC: Meadin-----	90	Poor Too sandy Low content of organic matter Droughty Too acid	0.00 0.12 0.29 0.97	Good		Poor Too sandy Rock fragments Hard to reclaim	0.00 0.00 0.00
MeE: Meadin-----	75	Poor Too sandy Low content of organic matter Droughty Too acid	0.00 0.12 0.29 0.97	Fair Slope	0.92	Poor Too sandy Rock fragments Hard to reclaim Slope	0.00 0.00 0.00 0.00

Section II
Soil and Site Information

Construction Materials Table 2
Gregory County, South Dakota

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The ratings given for the thickest layer are for the thickest layer above and excluding the bottom layer. The numbers in the value columns range from 0.00 to 0.99. The greater the value, the greater the likelihood that the bottom layer or thickest layer of the soil is a source of sand or gravel. See text for further explanation of ratings in this table.)

Map symbol and soil name	Pct. of map unit	Potential source of reclamation material		Potential source of roadfill		Potential source of topsoil	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
MoA: Millboro-----	90	Poor Too clayey Low content of organic matter Water erosion	0.00 0.12 0.99	Poor Shrink-swell Low strength	0.00 0.00	Poor Too Clayey	0.00
MoB: Millboro-----	90	Poor Too clayey Low content of organic matter Water erosion	0.00 0.12 0.99	Poor Shrink-swell Low strength	0.00 0.00	Poor Too Clayey	0.00
MoC: Millboro-----	90	Poor Too clayey Low content of organic matter Water erosion	0.00 0.12 0.99	Poor Shrink-swell Low strength	0.00 0.00	Poor Too Clayey	0.00
MpB: Millboro-----	55	Poor Too clayey Low content of organic matter Water erosion	0.00 0.12 0.99	Poor Shrink-swell Low strength	0.00 0.00	Poor Too Clayey	0.00
Lakoma-----	35	Poor Too clayey Droughty Depth to bedrock Carbonate content Water erosion	0.00 0.00 0.58 0.80 0.99	Poor Depth to bedrock Low strength Shrink-swell	0.00 0.00 0.00	Poor Too Clayey Depth to bedrock Carbonate content	0.00 0.58 0.80
MpC: Millboro-----	50	Poor Too clayey Low content of organic matter Water erosion	0.00 0.12 0.99	Poor Shrink-swell Low strength	0.00 0.00	Poor Too Clayey	0.00

Section II
Soil and Site Information

Construction Materials Table 2
Gregory County, South Dakota

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The ratings given for the thickest layer are for the thickest layer above and excluding the bottom layer. The numbers in the value columns range from 0.00 to 0.99. The greater the value, the greater the likelihood that the bottom layer or thickest layer of the soil is a source of sand or gravel. See text for further explanation of ratings in this table.)

Map symbol and soil name	Pct. of map unit	Potential source of reclamation material		Potential source of roadfill		Potential source of topsoil	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
Lakoma-----	40	Poor Too clayey Droughty Depth to bedrock Carbonate content Water erosion	0.00 0.00 0.58 0.80 0.99	Poor Depth to bedrock Low strength Shrink-swell	0.00 0.00 0.00	Poor Too Clayey Depth to bedrock Carbonate content	0.00 0.58 0.80
Mr: Mosher-----	75	Poor Sodium content Low content of organic matter Too clayey Salinity Water erosion	0.00 0.12 0.76 0.88 0.99	Fair Shrink-swell	0.59	Poor Salinity Too Clayey Sodium content Hard to reclaim	0.00 0.44 0.90 0.98
Ms: Mosher-----	55	Poor Sodium content Low content of organic matter Too clayey Salinity Water erosion	0.00 0.12 0.76 0.88 0.99	Fair Shrink-swell	0.59	Poor Salinity Too Clayey Sodium content Hard to reclaim	0.00 0.44 0.90 0.98
Jerauld-----	30	Poor Sodium content Low content of organic matter Too clayey Salinity Water erosion	0.00 0.12 0.32 0.88 0.99	Poor Low strength Shrink-swell	0.00 0.12	Poor Sodium content Salinity Too Clayey	0.00 0.00 0.19
ObE: Okaton-----	65	Poor Too clayey Droughty Depth to bedrock Water erosion	0.00 0.00 0.00 0.99	Poor Depth to bedrock Shrink-swell Low strength Slope	0.00 0.00 0.00 0.00	Poor Slope Too Clayey Depth to bedrock	0.00 0.00 0.00

Section II
Soil and Site Information

Construction Materials Table 2
Gregory County, South Dakota

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The ratings given for the thickest layer are for the thickest layer above and excluding the bottom layer. The numbers in the value columns range from 0.00 to 0.99. The greater the value, the greater the likelihood that the bottom layer or thickest layer of the soil is a source of sand or gravel. See text for further explanation of ratings in this table.)

Map symbol and soil name	Pct. of map unit	Potential source of reclamation material		Potential source of roadfill		Potential source of topsoil	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
Lakoma-----	35	Poor Too clayey Droughty Depth to bedrock Carbonate content Water erosion	0.00 0.00 0.58 0.80 0.99	Poor Depth to bedrock Low strength Shrink-swell Slope	0.00 0.00 0.00 0.08	Poor Slope Too Clayey Depth to bedrock Carbonate content	0.00 0.00 0.58 0.80
OcF: Okaton-----	55	Poor Too clayey Droughty Depth to bedrock Low content of organic matter Cobble content Water erosion	0.00 0.00 0.00 0.12 0.46 0.99	Poor Depth to bedrock Shrink-swell Low strength Slope	0.00 0.00 0.00 0.00	Poor Slope Too Clayey Rock fragments Depth to bedrock	0.00 0.00 0.00 0.00
Mariaville-----	30	Poor Depth to bedrock Droughty Low content of organic matter Water erosion	0.00 0.00 0.88 0.90	Poor Depth to bedrock Slope Low strength	0.00 0.00 0.00	Poor Slope Depth to bedrock	0.00 0.00
OeC: O'Neill-----	90	Fair Low content of organic matter Droughty Too acid	0.12 0.29 0.84	Good		Fair Hard to reclaim	0.92
On: Onita-----	90	Poor Too clayey Low content of organic matter Water erosion	0.00 0.12 0.90	Poor Low strength Shrink-swell	0.00 0.62	Poor Too Clayey	0.00
Or: Orthents, Loamy-----	70	Not rated		Not rated		Not rated	
Orthents, Shaly-----	30	Not rated		Not rated		Not rated	

Section II
Soil and Site Information

Construction Materials Table 2
Gregory County, South Dakota

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The ratings given for the thickest layer are for the thickest layer above and excluding the bottom layer. The numbers in the value columns range from 0.00 to 0.99. The greater the value, the greater the likelihood that the bottom layer or thickest layer of the soil is a source of sand or gravel. See text for further explanation of ratings in this table.)

Map symbol and soil name	Pct. of map unit	Potential source of reclamation material		Potential source of roadfill		Potential source of topsoil	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
Ot: Onita-----	90	Poor Too clayey Low content of organic matter Water erosion	0.00 0.12 0.90	Poor Low strength Shrink-swell	0.00 0.62	Poor Too Clayey	0.00
Pg: Orthents, Gravelly--	100	Poor Too sandy Droughty Low content of organic matter	0.00 0.05 0.12	Not Rated		Poor Too sandy Rock fragments Hard to reclaim	0.00 0.00 0.18
Pm: Platte-----	85	Poor Too sandy Droughty Low content of organic matter	0.00 0.07 0.12	Poor Depth to saturated zone	0.00	Poor Too sandy Depth to saturated zone Rock fragments Hard to reclaim	0.00 0.00 0.03 0.98
PrA: Promise-----	90	Poor Too clayey Low content of organic matter Water erosion	0.00 0.12 0.99	Poor Shrink-swell Low strength	0.00 0.00	Poor Too Clayey	0.00
PrB: Promise-----	90	Poor Too clayey Low content of organic matter Water erosion	0.00 0.12 0.99	Poor Shrink-swell Low strength	0.00 0.00	Poor Too Clayey	0.00
PrC: Promise-----	100	Poor Too clayey Low content of organic matter Water erosion	0.00 0.12 0.99	Poor Shrink-swell Low strength	0.00 0.00	Poor Too Clayey	0.00

Section II
Soil and Site Information

Construction Materials Table 2
Gregory County, South Dakota

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The ratings given for the thickest layer are for the thickest layer above and excluding the bottom layer. The numbers in the value columns range from 0.00 to 0.99. The greater the value, the greater the likelihood that the bottom layer or thickest layer of the soil is a source of sand or gravel. See text for further explanation of ratings in this table.)

Map symbol and soil name	Pct. of map unit	Potential source of reclamation material		Potential source of roadfill		Potential source of topsoil	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
RaA: Ree-----	90	Good		Poor Low strength Shrink-swell	0.00 0.99	Good	
RaB: Ree-----	90	Good		Poor Low strength Shrink-swell	0.00 0.99	Good	
RaC: Ree-----	90	Good		Poor Low strength Shrink-swell	0.00 0.99	Good	
RbA: Ree-----	85	Fair Too clayey Water erosion	0.98 0.99	Poor Low strength Shrink-swell	0.00 0.92	Fair Hard to reclaim Too Clayey	0.32 0.93
RcC: Ree-----	70	Good		Poor Low strength Shrink-swell	0.00 0.99	Good	
Tassel-----	20	Poor Droughty Depth to bedrock	0.00 0.00	Poor Depth to bedrock	0.00	Poor Depth to bedrock	0.00
ReA: Reliance-----	85	Fair Low content of organic matter Too clayey Water erosion	0.50 0.88 0.90	Poor Low strength Shrink-swell	0.00 0.72	Fair Too Clayey	0.57
ReB: Reliance-----	90	Fair Low content of organic matter Too clayey Water erosion	0.50 0.88 0.90	Poor Low strength Shrink-swell	0.00 0.72	Fair Too Clayey	0.57

Section II
Soil and Site Information

Construction Materials Table 2
Gregory County, South Dakota

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The ratings given for the thickest layer are for the thickest layer above and excluding the bottom layer. The numbers in the value columns range from 0.00 to 0.99. The greater the value, the greater the likelihood that the bottom layer or thickest layer of the soil is a source of sand or gravel. See text for further explanation of ratings in this table.)

Map symbol and soil name	Pct. of map unit	Potential source of reclamation material		Potential source of roadfill		Potential source of topsoil	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
ReB2: Reliance-----	90	Fair Low content of organic matter Too clayey Water erosion	0.50 0.88 0.90	Poor Low strength Shrink-swell	0.00 0.72	Fair Too Clayey	0.57
ReC: Reliance-----	90	Fair Low content of organic matter Too clayey Water erosion	0.50 0.88 0.90	Poor Low strength Shrink-swell	0.00 0.72	Fair Too Clayey	0.57
ReC2: Reliance-----	90	Poor Too clayey Low content of organic matter Water erosion	0.00 0.50 0.90	Poor Low strength Shrink-swell	0.00 0.66	Poor Too Clayey	0.00
ReD: Reliance-----	90	Fair Low content of organic matter Too clayey Water erosion	0.50 0.88 0.90	Poor Low strength Shrink-swell	0.00 0.72	Fair Slope Too Clayey	0.37 0.57
ReD2: Reliance-----	90	Fair Low content of organic matter Too clayey Water erosion	0.50 0.88 0.90	Poor Low strength Shrink-swell	0.00 0.72	Fair Slope Too Clayey	0.37 0.57
Rv: Riverwash-----	100	Not rated		Not rated		Not rated	

Section II
Soil and Site Information

Construction Materials Table 2
Gregory County, South Dakota

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The ratings given for the thickest layer are for the thickest layer above and excluding the bottom layer. The numbers in the value columns range from 0.00 to 0.99. The greater the value, the greater the likelihood that the bottom layer or thickest layer of the soil is a source of sand or gravel. See text for further explanation of ratings in this table.)

Map symbol and soil name	Pct. of map unit	Potential source of reclamation material		Potential source of roadfill		Potential source of topsoil	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
ScE: Sansarc-----	65	Poor Too clayey Droughty Depth to bedrock Low content of organic matter Water erosion	0.00 0.00 0.00 0.60 0.99	Poor Depth to bedrock Shrink-swell Low strength Slope	0.00 0.00 0.00 0.00	Poor Slope Too Clayey Depth to bedrock	0.00 0.00 0.00
Rock Outcrop, Soft--	30	Not rated		Not rated		Not rated	
So: Scott-----	85	Poor Too clayey Too acid Low content of organic matter Water erosion	0.00 0.84 0.88 0.90	Poor Depth to saturated zone Low strength Shrink-swell	0.00 0.00 0.55	Poor Too Clayey Depth to saturated zone	0.00 0.00
TrE: Tassel-----	70	Poor Droughty Depth to bedrock	0.00 0.00	Poor Depth to bedrock Slope	0.00 0.92	Poor Depth to bedrock Slope	0.00 0.00
Rock Outcrop, Sandstone-----	20	Not rated		Not rated		Not rated	
U1A: Uly-----	85	Fair Low content of organic matter Water erosion	0.12 0.90	Poor Low strength	0.00	Good	
U1B: Uly-----	85	Fair Low content of organic matter Water erosion	0.12 0.90	Poor Low strength	0.00	Good	

Section II
Soil and Site Information

Construction Materials Table 2
Gregory County, South Dakota

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The ratings given for the thickest layer are for the thickest layer above and excluding the bottom layer. The numbers in the value columns range from 0.00 to 0.99. The greater the value, the greater the likelihood that the bottom layer or thickest layer of the soil is a source of sand or gravel. See text for further explanation of ratings in this table.)

Map symbol and soil name	Pct. of map unit	Potential source of reclamation material		Potential source of roadfill		Potential source of topsoil	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
VaC: Valentine-----	85	Poor Too sandy Wind erosion Low content of organic matter Droughty	0.00 0.00 0.12 0.34	Good		Poor Too sandy	0.00
VaD: Valentine-----	85	Poor Too sandy Wind erosion Low content of organic matter Droughty	0.00 0.00 0.12 0.34	Good		Poor Too sandy Slope	0.00 0.04
Vt: Vetal-----	90	Fair Low content of organic matter	0.12	Good		Good	
W: Water (less Than 40 Acres)-----	100	Not rated		Not rated		Not rated	
Wd: Wendte-----	90	Poor Too clayey Low content of organic matter Water erosion	0.00 0.50 0.99	Poor Shrink-swell Low strength	0.00 0.00	Poor Too Clayey	0.00
We: Wendte-----	90	Poor Too clayey Water erosion	0.00 0.99	Poor Shrink-swell Low strength	0.00 0.00	Poor Too Clayey	0.00
Wh: Whitelake-----	90	Poor Sodium content Low content of organic matter Salinity	0.00 0.12 0.88	Good		Poor Sodium content Salinity	0.00 0.00

Section II
Soil and Site Information

Construction Materials Table 2
Gregory County, South Dakota

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The ratings given for the thickest layer are for the thickest layer above and excluding the bottom layer. The numbers in the value columns range from 0.00 to 0.99. The greater the value, the greater the likelihood that the bottom layer or thickest layer of the soil is a source of sand or gravel. See text for further explanation of ratings in this table.)

Map symbol and soil name	Pct. of map unit	Potential source of reclamation material		Potential source of roadfill		Potential source of topsoil	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
Wn: Witten-----	99	Poor Too clayey Low content of organic matter Water erosion	0.00 0.50 0.99	Poor Shrink-swell Low strength	0.00 0.00	Poor Too Clayey	0.00

